



Tabella delle temperature

		
40°C	2K Härter MS 25-40	2K Härter MS 25-40
30°C	2K Härter MS X 15-30	2K Härter MS 25-40 2K Härter MS X 15-30
20°C	2K Härter MS X 15-30 2K Härter MS X 5-25 2K Härter MS 5-15	2K Härter MS X 15-30
10°C	2K Härter MS X 5-25 2K Härter MS 5-15	2K Härter MS X 5-25
5°C		